



Dave Wei

From: "Gillpin, Robbin" <Robbin.Gillpin@Turbomeca.com>
To: <djwei1@redbarn.net>
Sent: Monday, August 20, 2007 6:43 PM
Subject: DESGIN.TM0430G001.02.A.pdf
Attach: DESGIN.TM0430G001.02.A.pdf

Dave, I believe the missing dimension is 4 mm from the center of the main pressure port.
The hole in question is to join the pressure relief valve to the main pressure port.
Please look at the attached and see if it makes sense to you.

P.S. Please make sure you use the correct pressure relief valve item # part no TM0430P006

Please let me know if there are any problems or questions.
Thanks Robbin